

Draft STAR Commissioning Schedule

Version 1.0, December 28, 2005.

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
January 1	2	3 Complete SGIS wiring changes	4 SGIS Checkout begins	5	6 DAQ & Run Control Ready for use	7
8 Blair returns	9 LN2 Cooldown starts SGIS trips checked with Sub Systems Beam Pipe Bakeout begins	10	11	12	13	14
15 Trigger Ready for Sub system use	16 AGS Cold Snake Comm. Begins TPC Setup & Test starts	17 FPD WN Work begins	18 Shield Wall assembled	19	20	21 Ar purge of TPC
22 P-10 purge of TPC	23 RHIC Dry Run begins TPC Gas Test begins	24	25 Gas test ends	26 Install West Poletip	27 EEMC Sect. 6 work begins	28
29	30 East Poletip installed	31 BBCs installed	February 1 He cooldown of Blue ring begins	2	3 FPD NW stacking done	4
5	6 Blue Ring Cold Magnet Testing, Day Shifts	7	8	9	10	11

February 13th, Both RHIC Rings at 4 K.